

DATE 0635Z 20 FEB 65

SECRET

TO : DIRECTOR

FROM [REDACTED] 25X1A

ACTION:

INFO :

TOR 0708Z 20 FEB 65

ROUTINE
9
10
11
12
13
14
15
16

PRIORITY

[REDACTED] IN 73004

TO PRIORITY [REDACTED]

7700 25X1A

25X1A

A. C045C

B. FAIR

C. NO MAJOR PROCESSING TROUBLES ENCOUNTERED. SOME
PROCESSING STREAKS AND PIN HOLES NOTED.

CAMERA STATIC ON S-R BURSTING ALONG BOTH EDGES.

FROM HEAD TO TAIL, APPROX 1 INCH IN FROM EDGES.

MINUS DENSITY MARKS ON S-L, 2 AND 3/4 INCHES IN
FROM THE CLOCK EDGE, AND REPEATING EVERY 1 AND 3/4 INCHES.

PLUS DENSITY LINE ON S-R-PARTS, 1-2-3 ONLY, AND IS
3 AND 3/8 INCHES IN FROM THE OUTBOARD EDGE.

METERING TROUBLE ON S-L-THE FIRST TWO FRAMES ARE
OVERLAPPED.

END OF MSG